

# Oil Field Environmental Incident Summary

**Incident:** 20160723162427      **Date/Time of Notice:** 07/23/2016 16:24

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** BJARNE 2-29H

**Field Name:** PATENT GATE

**Well File #:** 25116

**Date Incident:** 7/23/2016

**Time Incident:** 06:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 151

**Rng:** 100

**Sec:** 29

**Qtr:**

**Location Description:**

**Submitted By:** Patrick Skillestad

**Received By:**

**Contact Person:** Patrick Skillestad  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Fire

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	200	Barrels	200	Barrels	200	barrels
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 8/10/2016

**Clean Up Concluded:** 8/5/2016

**Risk Evaluation:**

Emergency services were on site and extinguished the fire.

**Areal Extent:**

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Tanks and associated piping will be replaced. Most of the fluid was consumed in the fire. Any remaining fluid will be removed along with contaminated dike material.

**Wastes Disposal Location:** TBD

**Agencies Involved:** Local Fire Department

**Updates**

---

**Date:** 7/25/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release remained on location according to the report. NDIC retains oversight.